

New York State Department of Transportation

PIA Safety Flag NB23CTW010

By: Rehan Afridi

Flag Date: June 14, 2023

Superseding Information:

No Flags Superseded

Structure Information

BIN: 1065318

Feature Carried: 278I278IX2M23027

Feature Crossed: 6TH AVENUE

Orientation: 8 - NORTHWEST

Region: 11 - NEW YORK CITY

County: KINGS

Political Unit: City of NEW YORK

Approximate Year Built: 1962

Posted Load Matches Inventory : Yes

Bridge Load Posting (Tons) : Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp

Number of Spans: 322

Verbal Notification Information

Person Notified: Muhammad Mubeen

Date: June 14, 2023 1:45:00 PM

Of: NYSDOT Region 11

Signature Information

Signature: Rehan Afridi, P.E. 075185

Date: June 16, 2023

Reviewed By: Robert Kemp

Date: June 16, 2023

Attachments: 5

Flagged Elements**No Flagged Elements*****Flagged Condition Description***

This PIA Safety Flag No. NB23CTW010 is a New Flag.
Location: Span 158, Pier 157, Column C2 at the base.

At Span 158, Pier 157 Column C2, End face, there is a broken electrical junction box which exhibits exposed live wires. The condition is at the base of the column, and is accessible by the public.

The subject location is at 40th Street and 3rd Avenue westbound.


Flag PhotographsPhoto Number: **1**Photo Filename: **Flag Location - Span 158 RA.jpg****Attachment Description: Flag Location Plan.**

Photo Number: 2

Photo Filename: IMG_2736.JPG



Attachment Description: General view of Flagged location. Looking Begin.

Photo Number: 3

Photo Filename: IMG_2737.JPG



Attachment Description: Location of Flagged condition at Pier 157, Column C2. Looking Begin.

Photo Number: 4

Photo Filename: IMG_2738.JPG



Attachment Description: Close-up view of the broken junction box at Column C2. Looking Begin.

Photo Number: 5

Photo Filename: IMG_2739.JPG



Attachment Description: Non-contact voltage detector indicates live wires at the junction box. Looking Begin.